



# Wyoming State Fire Marshal

Occupancy: **Absaroka Head Start Basin**

Occupancy ID: **686**

Address: **609 Rue ST  
Basin WY 82410**

Inspection Type: **Reinspection**

Inspection Date: **9/12/2022**

By: Hudson, Nick (0000053946)

Time In: **08:27**

Time Out: **00:01**

Authorized Date: **09/15/2022**

By: Hudson, Nick (0000053946)

Next Inspection Date: **No Inspection Scheduled**

Form: Maintenance E.

## Inspection Description:

Educational Group Occupancies includes, among others, the use of a building or structure, or a portion thereof, by 6 or more persons at any one time for educational purposes through the 12th grade.

## Inspection Topics:

### General Comments

All fire code violations identified during previous inspections have been corrected.

Thank You

**Status:** PASS

**Notes:**

## Exits


1008.3.2; Means of egress illuminated at all times. emergency power supply

In the event of power supply failure in rooms and spaces that require two or more means of egress an emergency electrical system shall automatically illuminate all of the following areas: In the event of power supply failure, in buildings that require two or more means of egress, an emergency electrical system shall automatically illuminate all of the following areas: The emergency power system shall provide power for a duration of not less than 90 minutes and shall consist of storage batteries, unit equipment or an on-site generator. The installation of the emergency power system shall be in accordance with Section 2702 of the International Building Code.

**Status:** PASS

**Notes:** Emergency light is not working. Replace the battery or replace the light

9-12-22 The light has been replaced and is functioning.



**Electrical**

603.2.2; Open electrical terminations.

Open junction boxes and open-wiring splices shall be prohibited. Approved covers shall be provided for all switch and electrical outlet boxes.

**Status:** PASS

**Notes:** Light switch cover in utility room  
9-12-22 Light switch cover is installed.



**Additional Time Spent on Inspection:**

Category	Start Date / Time	End Date / Time
----------	-------------------	-----------------

**Notes:** No Additional time recorded

**Total Additional Time: 0 minutes**

**Inspection Time: 0 minutes**

**Total Time: 0 minutes**

**Summary:**

**Overall Result:** Passed

Maintenance and plan review projects when no corrections are needed and all inspections are completed.

**Inspector Notes:**

**Inspector:**

Name: Hudson, Nick  
Rank: Fire Inspector  
Mobile Phone(s): None on file  
Email(s): nick.hudson@wyo.gov  
Hudson, Nick:

Signed on: 09/15/2022 08:32

\_\_\_\_\_  
Signature

\_\_\_\_\_  
Date

**Representative Signature:**

*Dandy Hammer*  
Signature

*9.16.22*  
Date