



Inspection Report

Inspection and Compliance Orders

Business Name: Sweet Spirits Child Care
Occupant Email:

Current Date: 11/07/2024 12:36

Address: 211 East Kelly Avenue, Jackson, WY 83002

Inspection Number: 202411071797

Inspection Date: 11/07/2024

Inspection Type: Re-Inspection

Primary Contact

Contact Wolf, Jennifer

Work Phone 302-562-5762

Email Sweetspiritschildcare@gmail.com

Cell Phone 307-264-1667

Inspection Details

Passed (Y/N): Yes

Violation Count: 3

Inspection Notes

Inspection Notes: All items have been taken care of. Thank you.

Violations

Violations

Violation Code	Violation Details	Repaired Date	Violation Status	Comments
907.10	Smoke alarms shall be tested and maintained in accordance with the manufacturer's instructions. Smoke alarms shall be replaced when they fail to respond to operability tests, or when they exceed 10 years from the date of manufacture, unless an earlier replacement is specified in the manufacturer's published instructions.	11/07/2024 11:33:49	Violation Repaired	The smoke alarms in the main room and the left bedroom are over 10 years old and shall be replaced. Smoke alarm has been replaced
1031.2.1	Operational constraints and opening control devices. Emergency escape and rescue openings shall be operational from inside the room without the use of keys or tools. Window-opening control devices complying with ASTM F2090 shall be permitted for use on windows serving as a required emergency escape and rescue opening.	11/07/2024 11:32:49	Violation Repaired	Please remove the book case from in front of the bedroom window in the left bedroom. It is blocking the window. Photo provided of windows being clear

Current Date: 11/07/2024 12:36


Business Name: Sweet Spirits Child Care

703.1	Materials and firestop systems used to protect membrane and through penetrations in fire-resistance-rated construction and construction installed to resist the passage of smoke shall be maintained. The materials and firestop systems shall be securely attached to or bonded to the construction being penetrated with no openings visible through or into the cavity of the construction. Where the system design number is known, the system shall be inspected to the listing criteria and manufacturer's installation instructions.	11/07/2024 11:33:18	Violation Repaired	Please re-install the access panel in the ceiling of the left bedroom Access panel has been reinstalled
-------	---	------------------------	-----------------------	--

Signatures

Signatures

Name	Contact/Inspector	Date	Signature
------	-------------------	------	-----------

Hudson , Nick	Inspector	11/07/2024	
---------------	-----------	------------	--

Inspector: Hudson, Nick

Inspector Contact Info: nick.hudson@wyo.gov 307-851-0278

Attachments

Inspection Documents

Violation Documents

Current Date: 11/07/2024
12:36

Any overlooked hazardous condition and/or violation does not imply approval of such conditions or violations